



HEAVY DUTY STRAPPING TOOLS

MANUAL NO. 13321



OPERATION INSTRUCTIONS

1. As shown in the picture, the packing strapping is tied around the box, and the two ends of the packing strapping are respectively snapped into the two ends of the buckle.



2. As shown in the picture, place the lower packing strapping under the lower tooth plate and the cutter body, and slide the upper packing strapping tie into the cutter groove and the spindle groove.



3. While holding the tool with your left hand, push and pull the handle back and forth with your right hand until the packing strapping is tightened.



4. Press down on the handle of the tool with your right hand, and after cutting off the strapping, press the handle tool firmly to the right to remove it.



5. Packing is complete!



Contact

Feel free to visit our website:

www.ussolid.com

You can email us at service@ussolid.com